

Network Disclosure Announcement No. 783

Short Term Public Notice Under Rule 51.333(a)

CenturyLink's Internet address: <u>http://www.centurylink.com/disclosures/</u> Copper Retirements in Arizona, Minnesota, and Oregon.

| First Implementation Date: | July 1, 2015 |
|------------------------------|--------------|
| Original Date Posted: | May 19, 2015 |

Summary:

Copper Retirements are necessary to respond to various factors in the Outside Plant, including road construction, maintenance problems, and growth accommodation. Replacement cables may be either copper or fiber. Specific information will be provided with each disclosure.

Locations, Timing of Deployments & Interface Requirements:

The following gives additional details on the copper retirement(s):

| STATE | WIRE CENTER | PLANNED COMPLETION OR RETIREMENT DATE | DA (s) | Job # | Replacing |
|-------|-------------------------------|---|--|--|--|
| AZ | Tucson Cortaro TCSNAZCO | 07-01-2015 | 212715, 212716, 210113, 210111, 210211, 212011, 212015 | E.714249 E.714164 E.714280 E.714029 | Growth in distribution area requires CenturyLink to cut facilites to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available. |

| STATE | WIRE CENTER | PLANNED COMPLETION OR RETIREMENT DATE | DA (s) | Job # | Replacing |
|-------|--------------------------|---|----------------|----------|--|
| AZ | Tucson South TCSNAZSO | 09-01-2015 | 111711, 111311 | E.692762 | Growth in distribution area requires CenturyLink to cut facilites to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available. |
| MN | Fergus Falls FRFLMNFB | 07-31-2015 | 181002 | E.675748 | Growth in distribution area requires CenturyLink to cut facilites to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available. |
| MN | Rochester ROCHMNRO | 10-30-2015 | 1612022 | E.710827 | Growth in distribution area requires CenturyLink to cut facilites to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available. |

| STATE | WIRE CENTER | PLANNED COMPLETION OR RETIREMENT DATE | DA (s) | Job # | Replacing |
|-------|-------------------------------|---|------------------------|----------|--|
| MN | Shoreview Rice SHVWMNRI | 10-09-2015 | 311303 | E.755274 | Growth in distribution area requires CenturyLink to cut facilites to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available. |
| OR | Albany ALBYOR63 | 07-31-2015 | 113511, 110961, 111412 | E.609084 | Growth in distribution area requires CenturyLink to cut facilites to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available. |

Additional Information:

Any customer premises equipment vendor/manufacturer or enhanced services provider desiring additional technical information in conjunction with this Disclosure can contact:

Abdennaceur Boudhaouia Regulatory Compliance Manager 303-707-8561 Jamal.Boudhaouia@CenturyLink.com